



PROD.# 431389
0515B

BEFORE USING THIS PRODUCT, PLEASE READ THIS ENTIRE LABEL.
FOR ADDITIONAL INFORMATION REFERENCE THE PRODUCT SAFETY DATA SHEET (SDS).

X-607

Locomotive Cleaner

DIRECTIONS:

LOW PRESSURE SPRAYAPPLICATION: For normal to heavily soiled surfaces, mix Zep® X-607 with 5 to 15 parts water. For lightly soiled surfaces, mix Zep X-607 with 20 to 40 parts water. Application to be made through drive-through spray arch (first arch).

1. Apply to thoroughly wet all surfaces of locomotive.
2. Follow with application of acid detergent through second arch or with a second application of Zep X-607.
3. Remove soils and detergent from locomotive with "spinner arch" followed by thorough freshwater rinse.



Danger:

Causes severe skin burns and eye damage. **Prevention:** Wash skin thoroughly after handling. Wear protective gloves/ protective clothing/ eye protection/ face protection. **Response:** IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. IF ON SKIN (or hair): Remove/ Take off immediately all contaminated clothing. Rinse skin with water/ shower. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/ physician. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/ physician. Wash contaminated clothing before reuse. **Storage:** Store locked up. **Disposal:** Dispose of contents/container in accordance with local regulation.

05/15

Supplemental Information:


DISPOSAL AND/OR SPILL INFORMATION: As with all cleaning and maintenance procedures, run-off from the cleaning or maintenance process should be diverted to a collection vessel or where permitted, to a sanitary sewer (consult local and state regulations) and not allowed to soak into the ground or to enter a storm sewer. If this product is spilled or contaminated and cannot be used, creating the need for disposal, absorb product on an inert absorbent material, and deposit in a clean container for disposal according to local authorities. Rinse area well with water. **STORAGE:** Store tightly-closed container in dry area at temperatures between 40° (4°C) and 120°F (49°C). DO NOT store at temperatures below 32°F (0°C). Keep this product away from food and food products.

Q261

Batch Code#



275 Gallons
1040.9 Liters



KEEP OUT OF REACH OF CHILDREN
FOR INDUSTRIAL AND INSTITUTIONAL USE ONLY
NOT FOR HOUSEHOLD USE OR RESALE

PRECAUCION

AL USUARIO: Si usted no lee inglés, no use este producto hasta que la etiqueta le haya sido explicada ampliamente. (TO THE USER: If you cannot read English, do not use this product until the label has been fully explained to you.)

This product is designed exclusively for industrial and institutional use by trained, professional maintenance personnel. Label directions and precautions must be followed exactly. Zep Inc. will not be responsible for any injury, loss, or damage if product is used in any manner not in compliance with label directions, or if precautions are not observed.

MADE IN USA
A Zep Inc. Brand
Distributed by:
Zep Sales & Service
1310 Seaboard Ind. Blvd.
Atlanta, GA 30318
www.zep.com
1-877 I BUY ZEP

U493-1